## **Applicant**

Item #\_ 4E Date: 11 24 25

Name of Legal Entity: DENIZ GRACY LLC

Business Name (DBA) : EL MEZCALITO

Business Type: Limited Liability Company

Insurance Company: SOCIETY INSURANCE

## **Premises Address**

**Mailing Address** 

Street: 1210 6TH

ST

Suite/Apt: 101

City: NEVADA

County: STORY

State: IOWA

ZIP: 50201-15

48

Street: 1210 6TH

ST

Suite/Apt: 101

City: NEVADA

County: STORY

State: IOWA

ZIP: 50201-15

48

## **Application Information**

Application ID : 0-009-425-857

Application Type: Class "C" Retail Alcohol License (LC) Renewal

Current Stage : Local Authority Review

Premises Type: Restaurant

Term: 12 months

Effective Date: 18-Nov-2025

Expiration Date: 17-Nov-2026

Inspection No:	25-236
Inspection Date:	11/13/2025
Inspection Time:	0.5
Inspected By:	

## NEVADA PUBLIC SAFETY DEPARTMENT FIRE INSPECTION REPORT



	Inspection and Co	omplianc	e Orders		
Facility:	El Mezcalito	Address:	1200 6th Street		
Phone:	515-288-3188	Address.			
Fax:		City:	City of Nevada		
Email:	mariadeniz99@icloud.com	State:	IA	Postal Code:	50201
ing see the second	Primary	Contact			
Contact:		Work:			
Email:		Cell:			

Inspection Type:

Inspection Notes:

Violation Code	Days to Correct*	Violation	Notes	Location
314.2		Fixtures and displays. Fixtures and displays of goods for sale to the public shall be arranged so as to maintain free, immediate and unobstructed access to exits as required by Chapter 10.	Blocked by Fake plants and a table.	south exit door
1008.3.2		Illumination level under emergency power. Emergency lighting facilities shall be arranged to provide initial illumination that is not less than an average of 1 footcandle (11 lux) and a minimum at any point of 0.1 footcandle (1 lux) measured along the path of egress at floor level. Illumination levels shall be permitted to decline to 0.6 footcandle (6 lux) average and a minimum at any point of 0.06 footcandle (0.6 lux) at the end of the emergency lighting time duration. A maximum-to-minimum illumination uniformity ratio of 40 to 1 shall not be exceeded. In Group I-2 occupancies, failure of a single lamp in a luminaire shall not reduce the illumination level to less than 0.2 footcandle (2.2 lux).	The emergency light near the south door test button was broke and did not work properly.	south exit sign and emergency lights
603.6		Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors.	Extension cords are not permitted to be used in place of permanent wiring. Remove all extension cords and replace with permanent outlets.	throughout kitchen and prep area.
601.1		Scope. The provisions of this chapter shall apply to the installation, operation, testing and maintenance of the following building services and systems: 1.Electrical systems, equipment and wiring. 2.Information technology server rooms. 3.Elevator systems, emergency operation and recall. 4.Fuel-fired appliances, heating systems, chimneys and fuel oil storage. 5.Commercial cooking equipment and systems. 6.Commercial cooking oil storage. 7.Mechanical refrigeration systems. 8.Hyperbaric facilities. 9.Clothes dryer exhaust systems.	Several outlets in the kitchen have broken ground connector ports from people pulling cords out forcefully. There was a plug ground plug stuck in the outlet under the TV in the dining room. An electrical cover plate was missing from the outlet in the kitchen by the stove.	several outlets in the kitchen

Inspector: Ray Reynolds		
	RAN	

A variance procedure is available. Please contact the inspector named for further assistance with this or any other matter.

<sup>\*</sup> Number of days to correct from date inspected.